

RELACIÓN ENTRE TEMPERATURAS, HUMEDAD RELATIVA Y PUNTO DE ROCÍO O CONDENSACIÓN

TEMPERATURA	HUMEDAD RELATIVA	PUNTO DE ROCÍO
16	40	2.4
16	50	5.5
16	60	8.2
16	70	10.5
16	80	12.5
18	40	4.15
18	50	7.4
18	60	10.8
18	70	12.5
18	80	14.5
20	40	6
20	50	9.2
20	60	12
20	70	14.4
20	80	16.5
22	40	7.8
22	50	11
22	60	13.8
22	70	16.3
22	80	18.4
24	40	9.5
24	50	12.9
24	60	15.8
24	70	18.2
24	80	20.3
26	40	11.3
26	50	14.7
26	60	17.6
26	70	20.1
26	80	22.3
28	40	13
28	50	16.5
28	60	19.5
28	70	22
28	80	24.2